
Construction progress report

RIVERBEND COMMERCE CENTER / MIDDLETOWN, CT / FICTIONAL PROJECT

VISIT 04	PREVIOUS VISIT	PREPARED FOR
October 30, 2026	October 16, 2026	Example client



VIEW 01 / SITE OVERVIEW - SCHEMATIC, NOT AN AERIAL PHOTO

Visible changes at a glance


A Roof coverage shown on the west portion of the building.
B Materials are staged along the south building edge.
C The east access lane remains visible in this example.

SAMPLE ONLY


All dates, observations, project details and illustrations are fictional.

Compare the same view

VIEW 01 / MATCHED ORIENTATION / TWO ILLUSTRATIVE DATES



PREVIOUS / OCTOBER 16, 2026



CURRENT / OCTOBER 30, 2026

Example observation: roof coverage is visible on the west section in the later view.

Real reports use dated photos from consistent, safely accessible viewpoints.

Observations & photo register

CONCISE NOTES / TRACEABLE FILES / EASY HANDOFF

01 / Visual observations

A **West building section**

Roof coverage is shown in the current illustration.

B **South staging area**

Material bundles are shown near the building edge.

C **East access lane**

The lane is visible; access suitability was not assessed.

02 / Example photo register

01 - Site overview	2026-10-30_View-01_Overview.jpg
02 - West elevation	2026-10-30_View-02_West.jpg
03 - South staging	2026-10-30_View-03_Staging.jpg

03 / Delivery notes

A real delivery includes a private photo-folder link and the next planned visit. Photos are selected and labeled; original capture files are retained as agreed.

SCOPE OF THIS REPORT

Visual documentation only. No survey, measurements, engineering inspection, completion certification or verification of concealed work. Example filenames describe the intended handoff; no source photos are included in this sample.